

ZA070A Zero Air

Numéro de pièce: UK: 30-1610 (230v) |
EU: 30-1620 (230v) | US: 30-1630 (110v)




La description

Générateur zéro air pour le gaz du détecteur dans les applications GC, le générateur ZA070A élimine tous les hydrocarbures d'une source d'air comprimé avant qu'il n'entre dans votre instrumentation, garantissant les résultats les plus précis de votre détecteur.



Generator Details

- **Types de gaz:** Air
- **Compresseur intégré:** Non



Principales caractéristiques

- Produit un débit constant d'air de qualité zéro avec une teneur en hydrocarbures inférieure à 0,1 ppm
- Fonctionne 24h / 24 et 7j / 7 si nécessaire
- Un générateur peut alimenter plusieurs instruments
- Peu de pièces mobiles signifie peu de maintenance et garantit une longue durée de vie du générateur
- Configuration minimale requise
- Garantie complète sur site de 12 mois

Spécifications techniques

	ZA070A Zero Air
Type de gaz	Air
Débit de gaz max:	7L/min
Teneur en hydrocarbures:	0.1ppm
Pureté max:	0.1ppm THC
Temps de mise en route:	40 Minutes
Voltage:	230 ± 10% VAC
Fréquence:	50 HZ
Courant:	4.9 Amps
Température de fonctionnement max:	30°C / 86°F
Particules:	0.01µm
Taille (HxLxP) mm	880 x 430 x 410 mm
Taille (HxLxP) pouces	34,6 x 16,9 x 16,1 inches
Poids du générateur	64kg / 140,8lbs

[PEAK Protected]TM

Peak Scientific gas generators define the benchmark in reliability, convenience and performance in laboratories around the world, and come backed with a 12 month warranty. Beyond this period however you can ensure that your investment continues to be **[Protected]** by our comprehensive generator care cover.

Our world-class aftercare support packages deliver a program of scheduled preventative maintenance whilst giving you the reassurance of instant access to worldwide technical support and priority on-site response in the untimely event of a breakdown.

- For ordering parts visit: www.peakscientific.com/ordering/
- For service plans visit: www.peakscientific.com/service/service-plans/

Peak Scientific UK
Tel: +44 (0)141 812 8100
Fax: +44 (0)141 812 8200

Peak Scientific North America
Tel: +1-800-767-6532
Fax: +1-978-608-9503

Peak Scientific China
Tel: +86 21 5079 1190
Fax: +86 21 5079 1191
For a full list of our worldwide office locations, please visit:
Web: www.peakscientific.com
Email: discover@peakscientific.com

Peak Scientific's Quality Management System conforms to: ISO:9001

